

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
4-BALT,
18-

ST. MARY'S SEMINARY
600 N. Paca Street
Baltimore
Maryland

HABS No. MD-47

Photographs by Perry E. Borchers of the Ohio State University, 1974.

- MD-47-12 EAST AND NORTH FACADES FROM NE, ANGLED--INCLINED
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-801L.
- MD-47-13 EAST FACADE, SOUTH PAVILION, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-802L.
- MD-47-14 EAST FACADE, SOUTH PAVILION, FRONTAL--INCLINED
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-803R.
- MD-47-15 CENTRAL PORTION OF WEST (REAR) FACADE, FRONTAL--INCLINED
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-804L.
- MD-47-16 WEST FACADE, FRONTAL, DISTANT--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-805R.
- MD-47-17 WEST FACADE, ANGLED, DISTANT--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-806R.
- MD-47-18 MAIN ENTRANCE IN EAST FACADE, ANGLED--INCLINED
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-807R.
- MD-47-19 SOUTH FACADE OF NW WING, ANGLED--INCLINED
Copy photograph of photogrammetric plate
LC-HABS-GS05-B-1974-808.
- MD-47-20 CENTRAL PORTION OF EAST FACADE, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-809R.

ST. MARY'S SEMINARY
HABS No. MD-47
Index to Photographs
(Page 2)

- MD-47-10¹¹ STAIRWAY & MAIN ENTRANCE OF EAST FACADE, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-810L.
- MD-47-11¹² SOUTH FACADE, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-811R.
- MD-47-12¹³ NORTH FACADE OF SOUTH WING, GRAZING WEST FACADE, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-812L.
- MD-47-13¹⁴ EASTERN PORTION OF NORTH FACADE, FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-813L.
- MD-47-14¹⁵ EAST FACADE OF WEST WING PROJECTING FROM NORTH FACADE,
FRONTAL--LEVEL
Copy photograph of photogrammetric plate
LC-HABS-GS01-B-1974-814L.
- MD-47-15¹⁶ CORNICE AND ROOF AT SE CORNER, INCLINED--ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-815R.
- MD-47-16¹⁷ CORNICE AND ROOF AT SOUTH END OF EAST FACADE, INCLINED--FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-816R.
- MD-47-17¹⁸ SOUTH END OF SOUTH PAVILION AT EAST FACADE, UPPER
PORTION--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-817L.
- MD-47-18¹⁹ UPPER PORTION, CENTRAL CORNER OF SOUTH PAVILION OF EAST
FACADE--STRONGLY INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-818L.
- MD-47-19²⁰ UPPER PORTION, NORTH END OF SOUTH PAVILION OF EAST
FACADE--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-819L.

ST. MARY'S SEMINARY
HABS No. MD-47
Index to Photographs
(Page 3)

- MD-47-20²¹ CORNICE AND ROOF AT NE CORNER OF SOUTH PAVILION OF EAST
FACADE--INCLINED, ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-820L.
- MD-47-21²² CORNICE AND ROOF AT SE CORNER OF CENTRAL PAVILION OF EAST
FACADE--INCLINED, ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-821L.
- MD-47-22²³ CORNICE AND ROOF AT SOUTH END OF CENTRAL PAVILION OF EAST
FACADE--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-822R.
- MD-47-23²⁴ DORMER IN CENTER OF CENTRAL PAVILION OF EAST FACADE--INCLINED,
FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-823R.
- MD-47-24²⁵ CORNICE AND ROOF AT NE CORNER OF CENTRAL PAVILION OF EAST
FACADE--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-824L.
- MD-47-25²⁶ CORNICE AND ROOF AT SE CORNER OF NORTH PAVILION OF EAST FACADE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-825L.
- MD-47-26²⁷ CORNICE AND ROOF AT NE CORNER OF EAST FACADE--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-826L.
- MD-47-27²⁸ MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-827R.
- MD-47-28²⁹ MAIN ENTRANCE IN EAST FACADE--LEVEL, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-828L.
- MD-47-29³⁰ BASEMENT WINDOW AND GRILLE SOUTH OF MAIN ENTRANCE IN EAST
FACADE--LEVEL, FRONTAL NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-829R.

ST. MARY'S SEMINARY
HABS No. MD-47
Index to Photographs
(Page 4)

- MD-47-30³¹ SE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST FACADE--LEVEL,
ANGLED NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-830R.
- MD-47-31³² NE CORNER OF MAIN ENTRANCE STAIRWAY IN EAST FACADE--LEVEL,
ANGLED NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-831L.
- MD-47-32³³ CENTRAL HEIGHT OF CENTRAL PAVILION IN EAST FACADE--INCLINED,
FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-832L.
- MD-47-33³⁴ UPPER PORTION OF CENTRAL PAVILION IN EAST FACADE--INCLINED,
FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-833L.
- MD-47-34³⁵ UPPER PORTION OF EAST PAVILION ON SOUTH FACADE--INCLINED,
SLIGHTLY ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-834R.
- MD-47-35³⁶ SW CORNER OF EAST PAVILION ON SOUTH FACADE--INCLINED, ANGLED
NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-835L.
- MD-47-36³⁷ SW CORNER AND SOUTH FACADE--LEVEL, ANGLED, WIDE ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-836L.
- MD-47-37³⁸ WEST FACADE OF SOUTH WING OF WEST FACADE--SLIGHTLY INCLINED,
SLIGHTLY ANGLED, NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-837L.
- MD-47-38³⁹ DORMER IN WEST FACADE OF SOUTH WING OF WEST FACADE--STRONGLY
INCLINED, ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-838R.

ST. MARY'S SEMINARY
HABS No. MD-47
Index to Photographs
(Page 5)

- MD-47-39⁴⁰ CENTRAL PAVILION OF WEST FACADE--SLIGHTLY ANGLED, FRONTAL,
NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-839R.
- MD-47-40⁴¹ CORNICE AND DORMER OF CENTRAL PAVILION OF WEST FACADE--INCLINED,
ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-840R.
- MD-47-41⁴² CORNICE AND DORMER OF SOUTH FACADE OF NW WING--INCLINED, FRONTAL
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-841L.
- MD-47-42⁴³ BASE OF WEST FACADE OF NW WING--LEVEL, FRONTAL WIDE ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-842L.
- MD-47-43⁴⁴ WEST SIDE OF BAY AT NW CORNER OF BUILDING-- SLIGHTLY INCLINED,
ANGLED, NORMAL ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-843R.
- MD-47-44⁴⁵ NE CORNER OF BAY AT NW CORNER OF BUILDING-- LEVEL, ANGLED, WIDE
ANGLE
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-844L.
- MD-47-45⁴⁶ ROOF AND CORNICE AT NW CORNER OF EAST PAVILION OF NORTH
FACADE--INCLINED, ANGLED
Copy photograph of photogrammetric plate
LC-HABS-FS13-B-1974-845L.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MD,
4-BALT,
18-

Addendum to:

St. Mary's Seminary
600 North Paca Street
Baltimore
Maryland

HABS No. MD-47

MD-47-~~46~~

47

Photocopy of right-hand plate of photogrammetric stereopair, Perry E. Borchers, photographer, 1974. The original is a 5"x7" glass plate negative with the identification B1974-801R. A total of 45 stereopairs were made for the HABS collection shortly before the building was demolished. None have been plotted.
EAST (PACA STREET) ELEVATION FROM NORTHEAST WITH SURVEY CONTROL POINTS NOTED.